




MC1000


Quick Start Guide

<http://www.symbol.com> See User Guide for more information


POST IN WORK AREA




Front View



Cable Installation




Back View




Battery Installation


Battery Door Removal



Li-Ion Battery




AAA Batteries





Charging Instructions

⦿ = LED Indicator Location Slow Flash = Normal Charge Solid Amber = Full Charge

Note: AAA Batteries cannot be charged in the mobile computer.




Single Slot Serial/USB Cradle



Four Slot USB Cradle

OPTIMUM SCANNING POSITIONS



MC 1000 Scanning





012345



012345

Do Not Cover Scan Window With Finger





OPTIMUM UPRIGHT BODY POSTURE



AVOID EXTREME WRIST ANGLES



AVOID EXTREME WRIST ANGLES



OPTIMUM BODY POSTURE

Optimum Body Posture For Low Scanning



Alternate left And right knees



AVOID BENDING



AVOID REACHING



Alternate left And right hands

Optimum Body Posture for High Scanning



Use a ladder

Taking breaks and task rotation recommended

Local Contact: _____

