

Test Report

Verified code:020328

Report No.:H201812253096-02EN-G1

Customer: Fujian Newland Auto-ID Tech.Co.,Ltd.

Address: Newland Science & Technolgy Park, No. 1 Rujiang West Rd. Mawei, Fuzhou, P. R. China

Sample description: TD-LTE Wireless data terminal

Sample model: NLS-NFT10

Reference document: IEC 60529-2013 DEGREES OF PROTECTION PROVIDED BY ENCLOSURES(IP Code)
No. H201812253096 testing service orders

Receive sample date: 2019-01-16

Test date: 2019-01-22~2019-01-23

Test result: Meet the requirement

Tested LiYunLiang Inspected ZhangYingzi Approved BobChen

(Engineer) Li Yun liang (Deputy Director) Zhang Yingzi (Deputy Manager) [Signature]

GUANGZHOU GRG METROLOGY & TEST CO., LTD

Issued Date: 2019/2/12

APPROVED(04)

The report is just responsible for the tested sample; The report is not valid without our stamp. The report must not be partially duplicated without our written approval. If there is any objection concerning the report, please inform us within 15 days from the date of receiving the report.

GUANGZHOU GRG METROLOGY & TEST CO., LTD

Address: 163 Pingyun Rd., West of Huangpu Ave., Guangzhou (510656)

Tel: (+86) -020-38699960 FAX: (+86) -020-38698685 Web: <http://www.grgtest.com>

*Note: This report H201812253096-02EN-G1 is modified from the report H201812253096-02EN. The report H201812253096-02EN is superceded and invalid.



TEST REPORT

Report No.:H201812253096-02EN-G1

Page 2 Of 7

Test type	☒ Commissioning test ☐ Routine test ☐ Approval test ☐ Type test		
Sample source	☒ Commissioned units send sample ☐ Sampling		
Sample	Model	Quantity	Test No.
TD-LTE Wireless data terminal	NLS-NFT10	4	H201812253096-0007~ H201812253096-0010
Appearance of sample	Shape: ☒ Square ☐ Round ☐ Irregular ☐ Others _____ Color: ☒ Monochrome ☐ Multicolor _____ ☐ Others _____ Type: ☐ Mini ☒ Small ☐ Small and medium ☐ Medium ☐ Large		
Sample components and accessories	Components: / Accessories: /		
Packing status	☒ Outer Packing _____ ☐ No packing		
Sample quality before test	☒ Conformity product ☐ Non-conformity product ☐ Prototype ☐ Others		
Abnormal condition of sample before test	/		
Environment condition	Temperature: (20~25) °C Relative humidity: (32~37) %		
Test address	163 Pingyun Rd., West of Huangpu Ave., Guangzhou		

TEST REPORT

Report No.:H201812253096-02EN-G1

Page 3 Of 7

1. IPX7 Test

1.1 Test condition

1.1.1 Reference standard: IEC-60529-2013.

1.1.2 Immersion depth: 1m.

1.1.3 Test time: 30min.

1.2 Sample quantity

Samples information refers to table 1-1.

Table 1-1 Samples information

Sample	Model	Quantity	Test No.
TD-LTE Wireless data terminal	NLS-NFT10	2	H201812253096-0005, H201812253096-0006

1.3 Test requirements

After IPX7 test, no water should enter the EUT.

1.4 Test result

1.4.1 After IPX7 test, no water enter the EUT.

1.4.2 The EUT passed the IPX7 test.

TEST REPORT

Report No.:H201812253096-02EN-G1

Page 4 Of 7

1.5 Test photos



FIG. 1-1 Pre-test appearance inspection
H201812253096-0007



FIG. 1-2 After test appearance inspection
H201812253096-0007



FIG. 1-3 Pre-test appearance inspection
H201812253096-0008



FIG. 1-4 After test appearance inspection
H201812253096-0008

TEST REPORT

Report No.:H201812253096-02EN-G1

Page 5 Of 7



FIG. 1-5 Installation diagram



FIG. 1-6 Internal inspection

2. IP6X Test

2.1 Test condition

- 2.1.1 Reference standard: IEC-60529-2013.
- 2.1.2 Dust type: talcum powder.
- 2.1.3 Dust concentration: $2\text{kg}/\text{m}^3$.
- 2.1.4 Dust blowing method: continuous blowing dust.
- 2.1.5 Maximum pressure difference: 2kPa.
- 2.1.6 Gas extraction: 80 times the volume of the casing.
- 2.1.7 Pumping speed: greater than 40 times per hour, shell volume.
- 2.1.8 Test time: 2h.

2.2 Sample quantity

Samples information refers to table 2-1.

Table 2-1 Samples information

Sample	Model	Quantity	Test No.
TD-LTE Wireless data terminal	NLS-NFT10	2	H201812253096-0009, H201812253096-0010

TEST REPORT

Report No.:H201812253096-02EN-G1

Page 6 Of 7

2.3 Test requirements

After IP6X test, the EUT should be dust-free into the interior.

2.4 Test result

2.4.1 No dust inside the EUT.

2.4.2 The EUT passed the IP6X Test.

2.5 Test photos



FIG. 2-1 Pre-test appearance inspection
H201812253096-0009



FIG. 2-2 After test appearance inspection
H201812253096-0009



FIG. 2-3 Pre-test appearance inspection
H201812253096-0010



FIG. 2-4 After test appearance inspection
H201812253096-0010

TEST REPORT

Report No.:H201812253096-02EN-G1

Page 7 Of 7



FIG. 2-5 Installation diagram



FIG. 2-6 internal inspection

2. Test equipments

No.	Equipment	Serial No.	Due date	Testing item
1	Sand and dust test chamber	180258	2019-04-10	IP6X
2	Water storage tank	886474	2019-08-28	IPX7
3	Steel rule	882505	2019-05-17	With test equipment

-----End of Report-----